

Corvette Mechanic Paul Koerner Shares C6 Corvette Blank Clock Navigation Fix

Default C6 Navigation fix for a BLANK CLOCK AFTER BATTERY DISCONNECT!

Hello all you C6 owners with NAVIGATION!!! We all know the issues with the clocks going blank, well, here is the fix from Corvette engineering

Click the link below and download the file.

https://tis2web.akamai.gm.com/radio/corvette_gps_my_05_10_fix.zip

Burn the LOADING.KWI to a BLANK CD-R. Once this is completely burned and finished, go to your Corvette

#1 Make sure the vehicle is outside and the engine is running.

#2 On the radio display, press the Open/Close Faceplate Key

#3 Eject the map disc by pressing DVD Map Database Eject Key. Insert the Software Update Disc in the DVD Map Database Slot

The update will start automatically. You will see a progress bar on the screen. The update takes about 2 minutes. The vehicle logo will be seen once the update is completed.

Once you see the Corvette logo, remove the update disc and REINSTALL YOUR MAP DISC!

THIS IS NOT A MAP UPDATE< THIS IS ONLY FOR YOUR CLOCK BEING BLANK!

If you have any further questions, please post up.

Paul is a GM World Class Technician who wrenches on Corvettes and other GM vehicles at Key Chevrolet in Middletown, CT. I had asked him about this after a friend's C6 with Nav suddenly lost its clock and I remember him telling me to be patient as he said there would be a fix coming for this at some point.

All the best, and THANK YOU TO CORVETTE ENGINEERING for this fix, Paul